

Supplement

Title:	700PTP-1 I.S. Supplement Issue:	3	
Part Number:	2811824	Issue Date:	1/14
Print Date:	April 2007	Page Count:	1
Revision/Date:			

This supplement contains information necessary to ensure the accuracy of the above Instruction Sheet.

Change #1

Replace the **Replacement Parts** section with the following:

Hose Assembly, Fluke PN 2815723

Rebuild Kit, Fluke PN 3093412

Bleed Valve Assembly (Needle), Fluke PN 2844329

Handle Assembly Rebuild Kit, Fluke PN 3668409

Change #2, 57806

Under **Introduction**,

Change: Vacuum to -0.96 bar (-13.9 psi)

To: Vacuum to -0.87 bar (-12.7 psi)