



Johanson Technology



0896FB15A0100E

Part Number:	0896FB15A0100E
Manufacturer/Brand:	Johanson Technology
Product description	BALUN 863MHZ-928MHZ 50/100 0805
Datasheets:	 0896FB15A0100E.pdf
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	84738 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION


Specifications of 0896FB15A0100E

PART NUMBER	0896FB15A0100E
MANUFACTURER	Johanson Technology
DESCRIPTION	BALUN 863MHZ-928MHZ 50/100 0805
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	84738 pcs
DATA SHEET	 0896FB15A0100E.pdf
SERIES	-
RETURN LOSS (MIN)	11.7dB
PHASE DIFFERENCE	180° ±15°
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	0805 (2012 Metric)
OTHER NAMES	712-1473-1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	1.5dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 100 Ohm
FREQUENCY RANGE	863MHz ~ 928MHz
DETAILED DESCRIPTION	RF Balun 863MHz ~ 928MHz 50 / 100 Ohm 0805 (2012 Metric)

Related Tags

Johanson Technology 0896FB15A0100E	0896FB15A0100E Distributor	0896FB15A0100E Supplier
0896FB15A0100E Price	0896FB15A0100E Pictures	0896FB15A0100E Image
0896FB15A0100E PDF Datasheet	0896FB15A0100E Download Datasheet	0896FB15A0100E Datasheet
0896FB15A0100E Stock	Buy 0896FB15A0100E	Buy Johanson Technology 0896FB15A0100E
Johanson Technology 0896FB15A0100E	Johanson Technology Supplier	Johanson Technology Distributor
Johanson Technology 0896FB15A0100E	Johanson 0896FB15A0100E	Johanson Technology Inc. 0896FB15A0100E

Related Products

 0896100104 Manufacturers: Affinity Medical Technologies - a Molex company Description: CONN LOCKWASHER In stock: 212086 pcs RFQ	 0897005.N Manufacturers: Hamlin / Littelfuse Description: FUSE AUTO 5A 58VDC BLADE MINI In stock: 7099 pcs RFQ
 0896740611 Manufacturers: Affinity Medical Technologies - a Molex company Description: GASKET,SMA J,BULKHEAD/RG 405 SEM In stock: 3327 pcs RFQ	 0896BM15A0032E Manufacturers: Johanson Technology Description: BALUN 863MHZ-928MHZ 0805 6 LEAD In stock: 375922 pcs RFQ
 0896BM15E0025E Manufacturers: Johanson Technology Description: BALUN 863MHZ-928MHZ 50/50 0805 In stock: 368392 pcs RFQ	 0896BM15A0001E Manufacturers: Johanson Technology Description: BALUN 863MHZ-928MHZ 0805 In stock: 99853 pcs RFQ
 0897015.N Manufacturers: Hamlin / Littelfuse Description: FUSE AUTO 15A 58VDC BLADE MINI In stock: 3745 pcs RFQ	 0897003.N Manufacturers: Hamlin / Littelfuse Description: FUSE AUTO 3A 58VDC BLADE MINI In stock: 3091 pcs RFQ
 0897002.N Manufacturers: Hamlin / Littelfuse Description: FUSE AUTO 2A 58VDC BLADE MINI In stock: 5507 pcs RFQ	 0897004.N Manufacturers: Hamlin / Littelfuse Description: FUSE AUTO 4A 58VDC BLADE MINI In stock: 3036 pcs RFQ
 Authorized Distributor 08966 Manufacturers: 3M Description: 3M NO CLEANUP REPLACEMENT NO In stock: 2694 pcs RFQ	 0897010.N Manufacturers: Hamlin / Littelfuse Description: FUSE AUTO 10A 58VDC BLADE MINI In stock: 5991 pcs RFQ