

N/A



Image may be representation. See specifications for product details.

CDCLVP110VFRG4

Part Number:	CDCLVP110VFRG4
Manufacturer/Brand:	N/A
Product description	IC CLK BUFFER 2:10 3.5GHZ 32LQFP
Datasheets:	
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	15445 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of CDCLVP110VFRG4

PART NUMBER	CDCLVP110VFRG4
MANUFACTURER	N/A
DESCRIPTION	IC CLK BUFFER 2:10 3.5GHZ 32LQFP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	15445 pcs
DATA SHEET	
VOLTAGE - SUPPLY	2.375 V ~ 3.8 V
TYPE	Fanout Buffer (Distribution), Multiplexer
SUPPLIER DEVICE PACKAGE	32-LQFP (7x7)
SERIES	-
RATIO - INPUT:OUTPUT	2:10
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	32-LQFP
OUTPUT	LVPECL
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	HSTL, LVPECL
FREQUENCY - MAX	3.5GHz
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
DETAILED DESCRIPTION	Clock Fanout Buffer (Distribution), Multiplexer IC 2:10 3.5GHz 32-LQFP
BASE PART NUMBER	CDCLVP110

Related Tags

CDCLVP110VFRG4	CDCLVP110VFRG4 Distributor	CDCLVP110VFRG4 Supplier
CDCLVP110VFRG4 Price	CDCLVP110VFRG4 Pictures	CDCLVP110VFRG4 Image
CDCLVP110VFRG4 PDF Datasheet	CDCLVP110VFRG4 Download Datasheet	CDCLVP110VFRG4 Datasheet
CDCLVP110VFRG4 Stock	Buy CDCLVP110VFRG4	Buy CDCLVP110VFRG4
CDCLVP110VFRG4	Supplier	Distributor

Related Products

	CDCLVP110VF Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 7934 pcs RFQ		CDCLVP111VF Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 9064 pcs RFQ
	CDCLVP110MVFR Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 14837 pcs RFQ		CDCLVP111RHBR Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32QFN In stock: 7954 pcs RFQ
	CDCLVP1204EVM Manufacturers: N/A Description: EVAL MODULE FOR CDCLVP1204 In stock: 587 pcs RFQ		CDCLVP111RHB Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32QFN In stock: 12166 pcs RFQ
	CDCLVP111VFR Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 14177 pcs RFQ		CDCLVP110VFR Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 14446 pcs RFQ
	CDCLVP1102RGTT Manufacturers: N/A Description: IC CLK BUFFER 1:2 2GHZ 16QFN In stock: 24348 pcs RFQ		CDCLVP110MVFRG4 Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 11462 pcs RFQ
	CDCLVP110VFG4 Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 11455 pcs RFQ		CDCLVP111MVFREP Manufacturers: N/A Description: IC CLOCK BUFFER MUX 2:10 32LQFP In stock: 4577 pcs RFQ