



LM3705XBMM-232/NOPB

Part Number:	LM3705XBMM-232/NOPB
Manufacturer/Brand:	N/A
Product description	IC MPU SUPERVISOR 2.32V 10MSOP
Datasheets:	
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	3655 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION







Specifications of LM3705XBMM-232/NOPB

PART NUMBER	LM3705XBMM-232/NOPB
MANUFACTURER	N/A
DESCRIPTION	IC MPU SUPERVISOR 2.32V 10MSOP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	3655 pcs
DATA SHEET	
VOLTAGE - THRESHOLD	2.32V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	10-VSSOP
SERIES	-
RESET TIMEOUT	20 ms Minimum
RESET	Active High
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	10-TFSOP, 10-MSOP (0.118", 3.00mm Width)
OUTPUT	Push-Pull, Totem Pole
OTHER NAMES	*LM3705XBMM-232 *LM3705XBMM-232/NOPB LM3705XBMM-232/NOPBCT LM3705XBMM-232CT LM3705XBMM-232CT-ND LM3705XBMM232NOPB
OPERATING TEMPERATURE	-40°C ~ 85°C (TJ)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	3 (168 Hours)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Push-Pull, Totem Pole 1 Channel 10-VSSOP
BASE PART NUMBER	LM3705

Related Tags

LM3705XBMM-232/NOPB	LM3705XBMM-232/NOPB Distributor	LM3705XBMM-232/NOPB Supplier
LM3705XBMM-232/NOPB Price	LM3705XBMM-232/NOPB Pictures	LM3705XBMM-232/NOPB Image
LM3705XBMM-232/NOPB PDF Datasheet	LM3705XBMM-232/NOPB Download Datasheet	LM3705XBMM-232/NOPB Datasheet
LM3705XBMM-232/NOPB Stock	Buy LM3705XBMM-232/NOPB	Buy LM3705XBMM-232/NOPB
LM3705XBMM-232/NOPB	Supplier	Distributor

Related Products

 RFQ	LM3704YCMM-308/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 3.08V 10MSOP In stock: 87995 pcs	 RFQ	LM3704YCMMX-232 Manufacturers: N/A Description: IC MPU SUPERVISOR 10MSOP In stock: 6520 pcs
 RFQ	LM3705XBBP-463 Manufacturers: N/A Description: IC MPU SUPERVISR 4.63V 9MICROSMD In stock: 3615 pcs	 RFQ	LM3704YCMMX-308/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 10MSOP In stock: 116218 pcs
 RFQ	LM3705XBBP-232 Manufacturers: N/A Description: IC MPU SUPERVISR 2.32V 9MICROSMD In stock: 4286 pcs	 RFQ	LM3705XCMM-308/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 3.08V 10MSOP In stock: 4180 pcs
 RFQ	LM3705XDBP-463 Manufacturers: N/A Description: IC MPU SUPERVISR 4.63V 9MICROSMD In stock: 3648 pcs	 RFQ	LM3704YCMM-232/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 2.32V 10MSOP In stock: 99624 pcs
 RFQ	LM3705XDBP-232 Manufacturers: N/A Description: IC MPU SUPERVISR 2.32V 9MICROSMD In stock: 6176 pcs	 RFQ	LM3705XCBP-308 Manufacturers: N/A Description: IC MPU SUPERVISR 3.08V 9MICROSMD In stock: 5140 pcs
 RFQ	LM3705XDMM-232/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 2.32V 10MSOP In stock: 2829 pcs	 RFQ	LM3705XBMM-463/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 4.63V 10MSOP In stock: 6386 pcs

