



LM3701XCBP-308

Part Number:	LM3701XCBP-308
Manufacturer/Brand:	N/A
Product description	IC MPU SUPERVISR 3.08V 9MICROSMD
Datasheets:	
RoHs Status	 Contains lead / RoHS non-compliant
Stock Condition	3693 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION










Specifications of LM3701XCBP-308

PART NUMBER	LM3701XCBP-308
MANUFACTURER	N/A
DESCRIPTION	IC MPU SUPERVISR 3.08V 9MICROSMD
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
QUANTITY AVAILABLE	3693 pcs
DATA SHEET	
VOLTAGE - THRESHOLD	3.08V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	9-μSMD (1.41x1.41)
SERIES	-
RESET TIMEOUT	140 ms Minimum
RESET	Active High
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	9-VFBGA
OUTPUT	Push-Pull, Totem Pole
OTHER NAMES	LM3701XCBP-308TR
OPERATING TEMPERATURE	-40°C ~ 85°C (TJ)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	3 (168 Hours)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DETAILED DESCRIPTION	Supervisor Push-Pull, Totem Pole 1 Channel 9-μSMD (1.41x1.41)
BASE PART NUMBER	LM3701

Related Tags

LM3701XCBP-308	LM3701XCBP-308 Distributor	LM3701XCBP-308 Supplier
LM3701XCBP-308 Price	LM3701XCBP-308 Pictures	LM3701XCBP-308 Image
LM3701XCBP-308 PDF Datasheet	LM3701XCBP-308 Download Datasheet	LM3701XCBP-308 Datasheet
LM3701XCBP-308 Stock	Buy LM3701XCBP-308	Buy LM3701XCBP-308
LM3701XCBP-308	Supplier	Distributor

Related Products

 RFQ	LM3700XCBP-308/NOPB Manufacturers: N/A Description: IC MPU SUPERVISR 3.08V 9MICROSMD In stock: 5068 pcs	 RFQ	LM3701XBBP-420 Manufacturers: N/A Description: IC MPU SUPERVISOR 4.2V 9MICROSMD In stock: 4548 pcs
 RFQ	LM3700XCTPX-296/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 9USMD In stock: 6885 pcs	 RFQ	LM3702XCBP-308/NOPB Manufacturers: N/A Description: IC MPU SUPERVISR 3.08V 9MICROSMD In stock: 6507 pcs
 RFQ	LM3702YABP-290 Manufacturers: N/A Description: IC MPU SUPERVISOR 2.9V 9MICROSMD In stock: 6198 pcs	 RFQ	LM3702XCBPX-308 Manufacturers: N/A Description: IC MPU SUPERVISOR 9USMD In stock: 6378 pcs
 RFQ	LM3700XCTP-296/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR LLO 9MICROSMD In stock: 6282 pcs	 RFQ	LM3702YABP-308/NOPB Manufacturers: N/A Description: IC MPU SUPERVISR 3.08V 9MICROSMD In stock: 6613 pcs
 RFQ	LM3702XCTPX-308/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 3.08V 9USMD In stock: 5213 pcs	 RFQ	LM3700XCBP-290 Manufacturers: N/A Description: IC MPU SUPERVISOR 2.9V 9MICROSMD In stock: 4966 pcs
 RFQ	LM3702XCTP-308/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 3.08V 9-USMD In stock: 4523 pcs	 RFQ	LM3700XCBPX-290 Manufacturers: N/A Description: IC MPU SUPERVISOR 9USMD In stock: 5485 pcs