




A Renesas Company

Intersil



ISL88708IP829Z

Part Number:	ISL88708IP829Z
Manufacturer/Brand:	Intersil
Product description	IC SUPERVISOR MPU 2.92V 8DIP
Datasheets:	 ISL88708IP829Z.pdf
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	4827 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.


Specifications of ISL88708IP829Z

PART NUMBER	ISL88708IP829Z
MANUFACTURER	Intersil
DESCRIPTION	IC SUPERVISOR MPU 2.92V 8DIP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	4827 pcs
DATA SHEET	 ISL88708IP829Z.pdf
VOLTAGE - THRESHOLD	2.92V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	8-PDIP
SERIES	-
RESET TIMEOUT	140 ms Minimum
RESET	Active High/Active Low
PACKAGING	Tube
PACKAGE / CASE	8-DIP (0.300", 7.62mm)
OUTPUT	Open Drain, Push-Pull
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Through Hole
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Open Drain, Push-Pull 1 Channel 8-PDIP
BASE PART NUMBER	ISL88708

Related Tags

Intersil ISL88708IP829Z	ISL88708IP829Z Distributor	ISL88708IP829Z Supplier
ISL88708IP829Z Price	ISL88708IP829Z Pictures	ISL88708IP829Z Image
ISL88708IP829Z PDF Datasheet	ISL88708IP829Z Download Datasheet	ISL88708IP829Z Datasheet
ISL88708IP829Z Stock	Buy ISL88708IP829Z	Buy Intersil ISL88708IP829Z
Intersil ISL88708IP829Z	Intersil Supplier	Intersil Distributor
Intersil ISL88708IP829Z		

Related Products

 A Renesas Company ISL88708IB844Z-TK Manufacturers: Intersil Description: IC SUPERVISOR MPU 4.38V 8-SOIC In stock: 70973 pcs RFQ	 ISL88716IP826Z Manufacturers: Intersil Description: IC SUPERVISOR MPU 2.63V 8DIP In stock: 6688 pcs RFQ
 A Renesas Company ISL88708IB829Z-TK Manufacturers: Intersil Description: IC SUPERVISOR MPU 2.92V 8-SOIC In stock: 73137 pcs RFQ	 ISL88731AHRZ Manufacturers: Intersil Description: IC BATTERY CHRGR SMBUS 28-TQFN In stock: 27411 pcs RFQ
 ISL88708IP831Z Manufacturers: Intersil Description: IC SUPERVISOR MPU 3.09V 8DIP In stock: 3445 pcs RFQ	 A Renesas Company ISL88708IB844Z Manufacturers: Intersil Description: IC SUPERVISOR 4.38V 8-SOIC In stock: 62985 pcs RFQ
 A Renesas Company ISL88708IB831Z Manufacturers: Intersil Description: IC SUPERVISOR 3.09V 8-SOIC In stock: 71063 pcs RFQ	 A Renesas Company ISL88716IB826Z Manufacturers: Intersil Description: IC SUPERVISOR 2.63V 8-SOIC In stock: 67938 pcs RFQ
 A Renesas Company ISL88716IB826Z-TK Manufacturers: Intersil Description: IC SUPERVISOR MPU 2.63V 8-SOIC In stock: 68373 pcs RFQ	 ISL88708IP844Z Manufacturers: Intersil Description: IC SUPERVISOR MPU 4.38V 8DIP In stock: 5869 pcs RFQ
 ISL88708IP826Z Manufacturers: Intersil Description: IC SUPERVISOR MPU 2.63V 8DIP In stock: 5918 pcs RFQ	 A Renesas Company ISL88708IB831Z-TK Manufacturers: Intersil Description: IC SUPERVISOR MPU 3.09V 8-SOIC In stock: 57444 pcs RFQ