



ISL88708IB826Z-TK

Part Number:

ISL88708IB826Z-TK

Manufacturer/Brand:

Intersil

Product description

IC SUPERVISOR MPU 2.63V 8-SOIC

Datasheets:

PDF

ISL88708IB826Z-TK.pdf

RoHs Status

RoHS

Lead free / RoHS Compliant

Stock Condition

64798 pcs stock

Ship From

Hong Kong

Shipment Way

DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of ISL88708IB826Z-TK

PART NUMBER	ISL88708IB826Z-TK
MANUFACTURER	Intersil
DESCRIPTION	IC SUPERVISOR MPU 2.63V 8-SOIC
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	64798 pcs
DATA SHEET	PDF ISL88708IB826Z-TK.pdf
VOLTAGE - THRESHOLD	2.63V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	8-SOIC
SERIES	-
RESET TIMEOUT	140 ms Minimum
RESET	Active High/Active Low
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	8-SOIC (0.154", 3.90mm Width)
OUTPUT	Open Drain, Push-Pull
OTHER NAMES	ISL88708IB826Z-TKTR
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Open Drain, Push-Pull 1 Channel 8-SOIC
BASE PART NUMBER	ISL88708

Related Tags

Intersil ISL88708IB826Z-TK	ISL88708IB826Z-TK Distributor	ISL88708IB826Z-TK Supplier
ISL88708IB826Z-TK Price	ISL88708IB826Z-TK Pictures	ISL88708IB826Z-TK Image
ISL88708IB826Z-TK PDF Datasheet	ISL88708IB826Z-TK Download Datasheet	ISL88708IB826Z-TK Datasheet
ISL88708IB826Z-TK Stock	Buy ISL88708IB826Z-TK	Buy Intersil ISL88708IB826Z-TK
Intersil ISL88708IB826Z-TK	Intersil Supplier	Intersil Distributor
Intersil ISL88708IB826Z-TK		

Related Products

intersil A Renesas Company ISL88708IB831Z-TK Manufacturers: Intersil Description: IC SUPERVISOR MPU 3.09V 8-SOIC In stock: 57444 pcs RFQ	intersil A Renesas Company ISL88708IB829Z-TK Manufacturers: Intersil Description: IC SUPERVISOR MPU 2.92V 8-SOIC In stock: 73137 pcs RFQ
ISL88706IP831Z Manufacturers: Intersil Description: IC SUPERVISOR MPU 3.09V 8DIP In stock: 6855 pcs RFQ	intersil A Renesas Company ISL88708IB831Z Manufacturers: Intersil Description: IC SUPERVISOR 3.09V 8-SOIC In stock: 71063 pcs RFQ
intersil A Renesas Company ISL88707IB846Z-TK Manufacturers: Intersil Description: IC SUPERVISOR MPU 4.64V 8-SOIC In stock: 74343 pcs RFQ	ISL88707IP846Z Manufacturers: Intersil Description: IC SUPERVISOR MPU 4.64V 8DIP In stock: 4236 pcs RFQ