



AD9515BCPZ

Part Number:	AD9515BCPZ
Manufacturer/Brand:	ADI (Analog Devices, Inc.)
Product description	IC CLK BUFFER 1:2 1.6GHZ 32LFCSP
Datasheets:	 AD9515BCPZ.pdf
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	7592 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION









Specifications of AD9515BCPZ

PART NUMBER	AD9515BCPZ
MANUFACTURER	ADI (Analog Devices, Inc.)
DESCRIPTION	IC CLK BUFFER 1:2 1.6GHZ 32LFCSP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	7592 pcs
DATA SHEET	 AD9515BCPZ.pdf
VOLTAGE - SUPPLY	3.135 V ~ 3.465 V
TYPE	Fanout Buffer (Distribution), Divider
SUPPLIER DEVICE PACKAGE	32-LFCSP-VQ (5x5)
SERIES	-
RATIO - INPUT:OUTPUT	1:2
PACKAGING	Tray
PACKAGE / CASE	32-VFQFN Exposed Pad, CSP
OUTPUT	CMOS, LVDS, LVPECL
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	3 (168 Hours)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	Clock
FREQUENCY - MAX	1.6GHz
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
DETAILED DESCRIPTION	Clock Fanout Buffer (Distribution), Divider IC 1:2 1.6GHz 32-VFQFN Exposed Pad, CSP
BASE PART NUMBER	AD9515

Related Tags

ADI (Analog Devices, Inc.) AD9515BCPZ	AD9515BCPZ Distributor	AD9515BCPZ Supplier
AD9515BCPZ Price	AD9515BCPZ Pictures	AD9515BCPZ Image
AD9515BCPZ PDF Datasheet	AD9515BCPZ Download Datasheet	AD9515BCPZ Datasheet
AD9515BCPZ Stock	Buy AD9515BCPZ	Buy ADI (Analog Devices, Inc.) AD9515BCPZ
ADI (Analog Devices, Inc.) AD9515BCPZ	ADI (Analog Devices, Inc.) Supplier	ADI (Analog Devices, Inc.) Distributor
ADI (Analog Devices, Inc.) AD9515BCPZ	AD AD9515BCPZ	ADI (Analog Devices, Inc.) AD9515BCPZ
Analog Devices Inc. AD9515BCPZ	Analog Devices, Inc. AD9515BCPZ	

Related Products

 AD9514/PCBZ Manufacturers: ADI (Analog Devices, Inc.) Description: BOARD EVAL CLOCK 3CH AD9514 In stock: 360 pcs RFQ	 AD9516-1/PCBZ Manufacturers: ADI (Analog Devices, Inc.) Description: BOARD EVALUATION FOR AD9516-1 In stock: 474 pcs RFQ
 AD9514BCPZ Manufacturers: ADI (Analog Devices, Inc.) Description: IC CLK BUFFER 1:3 1.6GHZ 32LFCSP In stock: 7602 pcs RFQ	 AD9516-1BCPZ Manufacturers: ADI (Analog Devices, Inc.) Description: IC CLOCK GEN 2.5GHZ VCO 64-LFCSP In stock: 6899 pcs RFQ
 AD9515BCPZ-REEL7 Manufacturers: ADI (Analog Devices, Inc.) Description: IC CLK BUFFER 1:2 1.6GHZ 32LFCSP In stock: 15263 pcs RFQ	 AD9516-0BCPZ-REEL7 Manufacturers: ADI (Analog Devices, Inc.) Description: IC CLOCK GEN 2.8GHZ VCO 64-LFCSP In stock: 9319 pcs RFQ
 AD9514BCPZ-REEL7 Manufacturers: ADI (Analog Devices, Inc.) Description: IC CLK BUFFER 1:3 1.6GHZ 32LFCSP In stock: 11128 pcs RFQ	 AD9515/PCBZ Manufacturers: ADI (Analog Devices, Inc.) Description: BOARD EVAL CLOCK 2CH AD9515 In stock: 474 pcs RFQ
 AD9516-0BCPZ Manufacturers: ADI (Analog Devices, Inc.) Description: IC CLOCK GEN 2.8GHZ VCO 64-LFCSP In stock: 6105 pcs RFQ	 AD9516-0/PCBZ Manufacturers: ADI (Analog Devices, Inc.) Description: IC CLOCK GEN 2.8GHZ VCO 64-LFCSP In stock: 411 pcs RFQ
 AD9513BCPZ Manufacturers: ADI (Analog Devices, Inc.) Description: IC CLK BUFFER 1:3 800MHZ 32LFCSP In stock: 7084 pcs RFQ	 AD9513BCPZ-REEL7 Manufacturers: ADI (Analog Devices, Inc.) Description: IC CLK BUFFER 1:3 800MHZ 32LFCSP In stock: 7268 pcs RFQ