



CDCS503TPWRQ1

Part Number:	CDCS503TPWRQ1
Manufacturer/Brand:	N/A
Product description	IC CLK BUFFER 1:1 108MHZ 8TSSOP
Datasheets:	
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	132674 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of CDCS503TPWRQ1

PART NUMBER	CDCS503TPWRQ1
MANUFACTURER	N/A
DESCRIPTION	IC CLK BUFFER 1:1 108MHZ 8TSSOP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	132674 pcs
DATA SHEET	
VOLTAGE - SUPPLY	3 V ~ 3.6 V
TYPE	Buffer/Driver, Multiplier
SUPPLIER DEVICE PACKAGE	8-TSSOP
SERIES	Automotive, AEC-Q100
RATIO - INPUT:OUTPUT	1:1
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	8-TSSOP (0.173", 4.40mm Width)
OUTPUT	LVC MOS
OTHER NAMES	296-36576-2 CDCS503TPWRQ1-ND
OPERATING TEMPERATURE	-40°C ~ 105°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	3 (168 Hours)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	LVC MOS
FREQUENCY - MAX	108MHz
DIFFERENTIAL - INPUT:OUTPUT	No/No
DETAILED DESCRIPTION	Clock Buffer/Driver, Multiplier IC 1:1 108MHz 8-TSSOP (0.173", 4.40mm Width)
BASE PART NUMBER	CDCS503

Related Tags

CDCS503TPWRQ1	CDCS503TPWRQ1 Distributor	CDCS503TPWRQ1 Supplier
CDCS503TPWRQ1 Price	CDCS503TPWRQ1 Pictures	CDCS503TPWRQ1 Image
CDCS503TPWRQ1 PDF Datasheet	CDCS503TPWRQ1 Download Datasheet	CDCS503TPWRQ1 Datasheet
CDCS503TPWRQ1 Stock	Buy CDCS503TPWRQ1	Buy CDCS503TPWRQ1
CDCS503TPWRQ1	Supplier	Distributor

Related Products

	CDCS502PERF-EVM Manufacturers: N/A Description: EVAL PERFORMANCE MOD FOR CDCS502 In stock: 1051 pcs RFQ		CDCU2A877ZQLT Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 15289 pcs RFQ
	CDCU877ARHAR Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 40VQFN In stock: 20815 pcs RFQ		CDCS503PWR Manufacturers: N/A Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP In stock: 68875 pcs RFQ
	CDCU877AGQLT Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 2999 pcs RFQ		CDCS504TPWRQ1 Manufacturers: N/A Description: CLOCK FREQUENCY MULTIPLIER In stock: 68058 pcs RFQ
	CDCS502PWR Manufacturers: N/A Description: IC OSC CLOCK GENERATOR 8-TSSOP In stock: 89793 pcs RFQ		CDCU2A877ZQLR Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 19558 pcs RFQ
	CDCS501PWR Manufacturers: N/A Description: IC CLOCK GEN/BUFFER SSC 8TSSOP In stock: 64944 pcs RFQ		CDCS503PW Manufacturers: N/A Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP In stock: 116452 pcs RFQ
	CDCU877AGQLR Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 6514 pcs RFQ		CDCS502PW Manufacturers: N/A Description: IC OSC CLOCK GENERATOR 8-TSSOP In stock: 39244 pcs RFQ

