

N/A



Image may be representation. See specifications for product details.

TLV809K33DBVT

Part Number:	TLV809K33DBVT
Manufacturer/Brand:	N/A
Product description	IC VOLT SUPERVISOR 2.93V SOT23-3
Datasheets:	
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	209205 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of TLV809K33DBVT

PART NUMBER	TLV809K33DBVT
MANUFACTURER	N/A
DESCRIPTION	IC VOLT SUPERVISOR 2.93V SOT23-3
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	209205 pcs
DATA SHEET	
VOLTAGE - THRESHOLD	2.93V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	SOT-23-3
SERIES	-
RESET TIMEOUT	120 ms Minimum
RESET	Active Low
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	TO-236-3, SC-59, SOT-23-3
OUTPUT	Push-Pull, Totem Pole
OTHER NAMES	296-27716-2
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Push-Pull, Totem Pole 1 Channel SOT-23-3
BASE PART NUMBER	TLV809K33

Related Tags

TLV809K33DBVT	TLV809K33DBVT Distributor	TLV809K33DBVT Supplier
TLV809K33DBVT Price	TLV809K33DBVT Pictures	TLV809K33DBVT Image
TLV809K33DBVT PDF Datasheet	TLV809K33DBVT Download Datasheet	TLV809K33DBVT Datasheet
TLV809K33DBVT Stock	Buy TLV809K33DBVT	Buy TLV809K33DBVT
TLV809K33DBVT	Supplier	Distributor

Related Products

	TLV809J25DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.25V SOT23-3 In stock: 127686 pcs RFQ		TLV809KEVM-019 Manufacturers: N/A Description: EVAL MODULE FOR TLV809K33 In stock: 4017 pcs RFQ
	TLV809L30DBVT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.64V SOT23-3 In stock: 182640 pcs RFQ		TLV809K33DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 113449 pcs RFQ
	TLV809L30DBVR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.64V SOT23-3 In stock: 347716 pcs RFQ		TLV809I50DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 4.55V SOT23-3 In stock: 222034 pcs RFQ
	TLV809J25DBVT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.25V SOT23-3 In stock: 104662 pcs RFQ		TLV809K33DBVR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 427288 pcs RFQ
	TLV809L30DBZR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.64V SOT23-3 In stock: 374608 pcs RFQ		TLV809J25DBVR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.25V SOT23-3 In stock: 365584 pcs RFQ
	TLV809K33DBZR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 140247 pcs RFQ		TLV809J25DBZR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.25V SOT23-3 In stock: 404687 pcs RFQ