



A Renesas Company

Intersil



Image may be representation. See specifications for product details.

X9315UP

Part Number:	X9315UP
Manufacturer/Brand:	Intersil
Product description	IC XDCP 32-TAP 50K 3WIRE 8-DIP
Datasheets:	 X9315UP.pdf
RoHs Status	 Contains lead / RoHS non-compliant
Stock Condition	5336 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of X9315UP

PART NUMBER	X9315UP
MANUFACTURER	Intersil
DESCRIPTION	IC XDCP 32-TAP 50K 3WIRE 8-DIP
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
QUANTITY AVAILABLE	5336 pcs
DATA SHEET	 X9315UP.pdf
VOLTAGE - SUPPLY	5V
TOLERANCE	±20%
TEMPERATURE COEFFICIENT (TYP)	±300 ppm/°C
TAPER	Linear
SUPPLIER DEVICE PACKAGE	8-PDIP
SERIES	XDCP™
RESISTANCE - WIPER (OHMS) (TYP)	200
RESISTANCE (OHMS)	50k
PACKAGING	Tube
PACKAGE / CASE	8-DIP (0.300", 7.62mm)
OPERATING TEMPERATURE	0°C ~ 70°C
NUMBER OF TAPS	32
NUMBER OF CIRCUITS	1
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MEMORY TYPE	Non-Volatile
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
INTERFACE	Up/Down (U/D, INC, CS)
FEATURES	-
DETAILED DESCRIPTION	Digital Potentiometer 50k Ohm 1 Circuit 32 Taps Up/Down (U/D, INC, CS) Interface 8-PDIP
CONFIGURATION	Potentiometer
BASE PART NUMBER	X9315

Related Tags

Intersil X9315UP	X9315UP Distributor	X9315UP Supplier
X9315UP Price	X9315UP Pictures	X9315UP Image
X9315UP PDF Datasheet	X9315UP Download Datasheet	X9315UP Datasheet
X9315UP Stock	Buy X9315UP	Buy Intersil X9315UP
Intersil X9315UP	Intersil Supplier	Intersil Distributor
Intersil X9315UP		

Related Products

 A Renesas Company X9315US-2.7T1 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-SOIC In stock: 3334 pcs RFQ	 A Renesas Company X9315UMZT1 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP In stock: 47806 pcs RFQ
 A Renesas Company X9315US-2.7 Manufacturers: Intersil Description: IC DIGITAL POT 50K 32TP 8SOIC In stock: 5800 pcs RFQ	 A Renesas Company X9315US Manufacturers: Intersil Description: IC DIGITAL POT 50K 32TP 8SOIC In stock: 5333 pcs RFQ
 A Renesas Company X9315UPI Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-DIP In stock: 2798 pcs RFQ	 A Renesas Company X9315UMT1 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP In stock: 5263 pcs RFQ
 A Renesas Company X9315UMZ-2.7T1 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP In stock: 36730 pcs RFQ	 A Renesas Company X9315UP-2.7 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-DIP In stock: 3800 pcs RFQ
 A Renesas Company X9315UMZ Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP In stock: 31979 pcs RFQ	 A Renesas Company X9315UMZ-2.7 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP In stock: 29241 pcs RFQ
 A Renesas Company X9315UMIZT1 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP In stock: 40527 pcs RFQ	 A Renesas Company X9315UPI-2.7 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-DIP In stock: 6771 pcs RFQ