




Image may be representation. See specifications for product details.

ISL88706IB844Z-TK

Part Number:	ISL88706IB844Z-TK
Manufacturer/Brand:	Intersil
Product description	IC SUPERVISOR MPU 4.38V 8-SOIC
Datasheets:	ISL88706IB844Z-TK.pdf
RoHs Status	Lead free / RoHS Compliant
Stock Condition	62775 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of ISL88706IB844Z-TK

PART NUMBER	ISL88706IB844Z-TK
MANUFACTURER	Intersil
DESCRIPTION	IC SUPERVISOR MPU 4.38V 8-SOIC
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	62775 pcs
DATA SHEET	ISL88706IB844Z-TK.pdf
VOLTAGE - THRESHOLD	4.38V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	8-SOIC
SERIES	-
RESET TIMEOUT	140 ms Minimum
RESET	Active Low
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	8-SOIC (0.154", 3.90mm Width)
OUTPUT	Open Drain or Open Collector
OTHER NAMES	ISL88706IB844Z-TKTR
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Open Drain or Open Collector 1 Channel 8-SOIC
BASE PART NUMBER	ISL88706

Related Tags

Intersil ISL88706IB844Z-TK	ISL88706IB844Z-TK Distributor	ISL88706IB844Z-TK Supplier
ISL88706IB844Z-TK Price	ISL88706IB844Z-TK Pictures	ISL88706IB844Z-TK Image
ISL88706IB844Z-TK PDF Datasheet	ISL88706IB844Z-TK Download Datasheet	ISL88706IB844Z-TK Datasheet
ISL88706IB844Z-TK Stock	Buy ISL88706IB844Z-TK	Buy Intersil ISL88706IB844Z-TK
Intersil ISL88706IB844Z-TK	Intersil Supplier	Intersil Distributor
Intersil ISL88706IB844Z-TK		

Related Products

ISL88706IP831Z Manufacturers: Intersil Description: IC SUPERVISOR MPU 3.09V 8DIP In stock: 6855 pcs RFQ	ISL88706IB831Z Manufacturers: Intersil Description: IC SUPERVISOR 3.09V 8-SOIC In stock: 61743 pcs RFQ
ISL88707IB846Z Manufacturers: Intersil Description: IC SUPERVISOR 4.64V 8-SOIC In stock: 60696 pcs RFQ	ISL88706IB831Z-TK Manufacturers: Intersil Description: IC SUPERVISOR MPU 3.09V 8-SOIC In stock: 66009 pcs RFQ
ISL88706IB844Z Manufacturers: Intersil Description: IC SUPERVISOR 4.38V 8-SOIC In stock: 75902 pcs RFQ	ISL88706IB829Z Manufacturers: Intersil Description: IC SUPERVISOR 2.92V 8-SOIC In stock: 29875 pcs RFQ
ISL88706IP844Z Manufacturers: Intersil Description: IC SUPERVISOR MPU 4.38V 8DIP In stock: 6563 pcs RFQ	ISL88707IB846Z-TK Manufacturers: Intersil Description: IC SUPERVISOR MPU 4.64V 8-SOIC In stock: 74343 pcs RFQ
ISL88706IB826Z-TK Manufacturers: Intersil Description: IC SUPERVISOR MPU 2.63V 8-SOIC In stock: 58702 pcs RFQ	ISL88706IP826Z Manufacturers: Intersil Description: IC SUPERVISOR MPU 2.63V 8DIP In stock: 65247 pcs RFQ
ISL88706IB829Z-TK Manufacturers: Intersil Description: IC SUPERVISOR MPU 2.92V 8-SOIC In stock: 75046 pcs RFQ	ISL88706IP829Z Manufacturers: Intersil Description: IC SUPERVISOR MPU 2.92V 8DIP In stock: 2872 pcs RFQ