





A Renesas Company

Intersil




X4005M8I

| | |
|---------------------|--|
| Part Number: | X4005M8I |
| Manufacturer/Brand: | Intersil |
| Product description | IC SUPERVISOR CPU I2C 8-MSOP |
| Datasheets: |  X4005M8I.pdf |
| RoHs Status |  Contains lead / RoHS non-compliant |
| Stock Condition | 4400 pcs stock |
| Ship From | Hong Kong |
| Shipment Way | DHL/Fedex/TNT/UPS/EMS |

REQUEST FOR QUOTATION













Specifications of X4005M8I

| | |
|----------------------------------|--|
| PART NUMBER | X4005M8I |
| MANUFACTURER | Intersil |
| DESCRIPTION | IC SUPERVISOR CPU I2C 8-MSOP |
| LEAD FREE STATUS / ROHS STATUS | Contains lead / RoHS non-compliant |
| QUANTITY AVAILABLE | 4400 pcs |
| DATA SHEET |  X4005M8I.pdf |
| VOLTAGE - THRESHOLD | 4.38V |
| TYPE | Simple Reset/Power-On Reset |
| SUPPLIER DEVICE PACKAGE | 8-MSOP |
| SERIES | - |
| RESET TIMEOUT | 100 ms Minimum |
| RESET | Active High |
| PACKAGING | Tube |
| PACKAGE / CASE | 8-TSSOP, 8-MSOP (0.118", 3.00mm Width) |
| OUTPUT | Open Drain or Open Collector |
| OPERATING TEMPERATURE | -40°C ~ 85°C (TA) |
| NUMBER OF VOLTAGES MONITORED | 1 |
| MOUNTING TYPE | Surface Mount |
| MOISTURE SENSITIVITY LEVEL (MSL) | 1 (Unlimited) |
| LEAD FREE STATUS / ROHS STATUS | Contains lead / RoHS non-compliant |
| DETAILED DESCRIPTION | Supervisor Open Drain or Open Collector 1 Channel 8-MSOP |
| BASE PART NUMBER | X4005 |

Related Tags

| | | |
|------------------------|-----------------------------|-----------------------|
| Intersil X4005M8I | X4005M8I Distributor | X4005M8I Supplier |
| X4005M8I Price | X4005M8I Pictures | X4005M8I Image |
| X4005M8I PDF Datasheet | X4005M8I Download Datasheet | X4005M8I Datasheet |
| X4005M8I Stock | Buy X4005M8I | Buy Intersil X4005M8I |
| Intersil X4005M8I | Intersil Supplier | Intersil Distributor |
| Intersil X4005M8I | | |

Related Products

| | |
|--|--|
|  <div>X4005M8IZ-2.7A Manufacturers: Intersil Description: IC SUPERVISOR CPU I2C 8-MSOP In stock: 3598 pcs RFQ</div> |  <div>X4005M8IZ Manufacturers: Intersil Description: IC SUPERVISOR CPU I2C 8-MSOP In stock: 4175 pcs RFQ</div> |
|  <div>X4003S8Z-2.7A Manufacturers: Intersil Description: IC SUPERVISOR CPU I2C 8-SOIC In stock: 3969 pcs RFQ</div> |  <div>X4005M8I-2.7A Manufacturers: Intersil Description: IC SUPERVISOR CPU I2C 8-MSOP In stock: 6711 pcs RFQ</div> |
|  <div>X4005M8 Manufacturers: Intersil Description: IC SUPERVISOR CPU I2C 8-MSOP In stock: 2947 pcs RFQ</div> |  <div>X4005M8-2.7A Manufacturers: Intersil Description: IC SUPERVISOR CPU I2C 8-MSOP In stock: 5328 pcs RFQ</div> |
|  <div>X4005M8-2.7 Manufacturers: Intersil Description: IC SUPERVISOR CPU I2C 8-MSOP In stock: 5139 pcs RFQ</div> |  <div>X4005M8I-2.7 Manufacturers: Intersil Description: IC SUPERVISOR CPU I2C 8-MSOP In stock: 5664 pcs RFQ</div> |
|  <div>X4005M8I-4.5A Manufacturers: Intersil Description: IC SUPERVISOR CPU I2C 8-MSOP In stock: 2862 pcs RFQ</div> |  <div>X4005M8IZ-2.7 Manufacturers: Intersil Description: IC SUPERVISOR CPU I2C 8-MSOP In stock: 2944 pcs RFQ</div> |
|  <div>X4003S8Z-4.5A Manufacturers: Intersil Description: IC SUPERVISOR CPU I2C 8-SOIC In stock: 2982 pcs RFQ</div> |  <div>X4005M8-4.5A Manufacturers: Intersil Description: IC SUPERVISOR CPU I2C 8-MSOP In stock: 6730 pcs RFQ</div> |