

N/A



Image may be representation. See specifications for product details.

LM8364BALMF20

Part Number:	LM8364BALMF20
Manufacturer/Brand:	N/A
Product description	IC DETECT UNDERVOLT 2V SOT-23-5
Datasheets:	
RoHs Status	 Contains lead / RoHS non-compliant
Stock Condition	187295 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION


Specifications of LM8364BALMF20

PART NUMBER	LM8364BALMF20
MANUFACTURER	N/A
DESCRIPTION	IC DETECT UNDERVOLT 2V SOT-23-5
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
QUANTITY AVAILABLE	187295 pcs
DATA SHEET	
VOLTAGE - THRESHOLD	2V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	SOT-23-5
SERIES	-
RESET TIMEOUT	60 μs Typical Propagation Delay
RESET	Active Low
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	SC-74A, SOT-753
OUTPUT	Open Drain or Open Collector
OTHER NAMES	296-36243-2 LM8364BALMF20TR LM8364BALMF20TR-ND
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DETAILED DESCRIPTION	Supervisor Open Drain or Open Collector 1 Channel SOT-23-5
BASE PART NUMBER	LM8364

Related Tags

LM8364BALMF20	LM8364BALMF20 Distributor	LM8364BALMF20 Supplier
LM8364BALMF20 Price	LM8364BALMF20 Pictures	LM8364BALMF20 Image
LM8364BALMF20 PDF Datasheet	LM8364BALMF20 Download Datasheet	LM8364BALMF20 Datasheet
LM8364BALMF20 Stock	Buy LM8364BALMF20	Buy LM8364BALMF20
LM8364BALMF20	Supplier	Distributor

Related Products




LM833P
Manufacturers: N/A
Description: IC OPAMP AUDIO 16MHZ 8DIP
In stock: 89342 pcs

RFQ




LM833YDT
Manufacturers: STMicroelectronics
Description: IC OPAMP AUDIO 15MHZ 8SO
In stock: 133019 pcs

RFQ




LM8364BALMF30/NOPB
Manufacturers: N/A
Description: IC DETECT UNDERVOLT 3V SOT-23-5
In stock: 5513 pcs



LM8364BALMFX20
Manufacturers: N/A
Description: IC DETECTOR UNDERVOLT 2V SOT23-5
In stock: 3596 pcs

RFQ




LM8364BALMF20/NOPB
Manufacturers: N/A
Description: IC DETECT UNDERVOLT 2V SOT-23-5
In stock: 274757 pcs




LM8342SDX
Manufacturers: N/A
Description: IC TFT VCOM CALIBRATOR 10WSON
In stock: 3569 pcs

RFQ



LM8364BALMF27/NOPB
Manufacturers: N/A
Description: IC UNDER VOLTAGE SENS SOT23-5
In stock: 5962 pcs



LM8342SDX/NOPB
Manufacturers: N/A
Description: IC TFT VCOM CALIBRATOR 10WSON
In stock: 60021 pcs

RFQ




LM8364BALMF45/NOPB
Manufacturers: N/A
Description: IC DETECT UNDERVOLT 4.5V SOT23-5
In stock: 6926 pcs



LM8342SD
Manufacturers: N/A
Description: IC TFT VCOM CALIBRATOR 10WSON
In stock: 3312 pcs

RFQ



LM8342SD/NOPB
Manufacturers: N/A
Description: IC TFT VCOM CALIBRATOR 10WSON
In stock: 49811 pcs

RFQ



LM8364BALMF32/NOPB
Manufacturers: N/A
Description: IC UNDERVOLT SENSING CIR SOT23-5
In stock: 6670 pcs

RFQ

