



HHM1946A1

Part Number:	HHM1946A1
Manufacturer/Brand:	TDK Corporation
Product description	BALUN 2.3GHZ-2.7GHZ 50/100 0402
Datasheets:	 HHM1946A1.pdf
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	62622 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION



Specifications of HHM1946A1

PART NUMBER	HHM1946A1
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 2.3GHZ-2.7GHZ 50/100 0402
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	62622 pcs
DATA SHEET	 HHM1946A1.pdf
SERIES	-
RETURN LOSS (MIN)	-23dB
PHASE DIFFERENCE	190°
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	0402 (1005 Metric), 4 PC Pad
OTHER NAMES	445-173092-1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	0.5dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 100 Ohm
FREQUENCY RANGE	2.3GHz ~ 2.7GHz
DETAILED DESCRIPTION	RF Balun 2.3GHz ~ 2.7GHz 50 / 100 Ohm 0402 (1005 Metric), 4 PC Pad

Related Tags

TDK Corporation HHM1946A1	HHM1946A1 Distributor	HHM1946A1 Supplier
HHM1946A1 Price	HHM1946A1 Pictures	HHM1946A1 Image
HHM1946A1 PDF Datasheet	HHM1946A1 Download Datasheet	HHM1946A1 Datasheet
HHM1946A1 Stock	Buy HHM1946A1	Buy TDK Corporation HHM1946A1
TDK Corporation HHM1946A1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1946A1		

Related Products

 HHM1906A1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/75 0402 In stock: 3696 pcs RFQ	 HHM2202SA2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 1.71-1.79GHZ 0603 In stock: 4048 pcs RFQ
 HHM2215SA5 Manufacturers: TDK Corporation Description: RF DIR COUPLER 824-915MHZ 0603 In stock: 75095 pcs RFQ	 HHM22152A2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 450-3800MHZ 1608 In stock: 1092054 pcs RFQ
 HHM22137A2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 698-2620MHZ 0603 In stock: 1214475 pcs RFQ	 HHM1932A2 Manufacturers: TDK Corporation Description: BALUN 862MHZ-894MHZ 50/100 0402 In stock: 1054239 pcs RFQ
 HHM22106C1 Manufacturers: TDK Corporation Description: RF DIR CPLR 700MHZ-2.7GHZ 0603 In stock: 1052355 pcs RFQ	 HHM1917A5 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 In stock: 335006 pcs RFQ
 HHM2204SA1 Manufacturers: TDK Corporation Description: RF DIR COUPLR 1.71-1.785GHZ 0603 In stock: 237035 pcs RFQ	 HHM1907B1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/50 0402 In stock: 307944 pcs RFQ
 HHM1927A4 Manufacturers: TDK Corporation Description: BALUN 1.805-2.17GHZ 50/100 0402 In stock: 319228 pcs RFQ	 HHM1918A2 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 0402 In stock: 1190924 pcs RFQ