



TLV809L30DBVR

Part Number:	TLV809L30DBVR
Manufacturer/Brand:	N/A
Product description	IC VOLT SUPERVISOR 2.64V SOT23-3
Datasheets:	
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	347716 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION








Specifications of TLV809L30DBVR

PART NUMBER	TLV809L30DBVR
MANUFACTURER	N/A
DESCRIPTION	IC VOLT SUPERVISOR 2.64V SOT23-3
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	347716 pcs
DATA SHEET	
VOLTAGE - THRESHOLD	2.64V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	SOT-23-3
SERIES	-
RESET TIMEOUT	120 ms Minimum
RESET	Active Low
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	TO-236-3, SC-59, SOT-23-3
OUTPUT	Push-Pull, Totem Pole
OTHER NAMES	296-39292-2 TLV809L30DBVR-ND
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Push-Pull, Totem Pole 1 Channel SOT-23-3
BASE PART NUMBER	TLV809L30

Related Tags

TLV809L30DBVR	TLV809L30DBVR Distributor	TLV809L30DBVR Supplier
TLV809L30DBVR Price	TLV809L30DBVR Pictures	TLV809L30DBVR Image
TLV809L30DBVR PDF Datasheet	TLV809L30DBVR Download Datasheet	TLV809L30DBVR Datasheet
TLV809L30DBVR Stock	Buy TLV809L30DBVR	Buy TLV809L30DBVR
TLV809L30DBVR	Supplier	Distributor

Related Products

	TLV809KEVM-019 Manufacturers: N/A Description: EVAL MODULE FOR TLV809K33 In stock: 4017 pcs RFQ		TLV810RDBZR Manufacturers: N/A Description: IC VOLT SUPERVISR 2.64V SOT23-3 In stock: 179285 pcs RFQ
	TLV809L30DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.64V SOT23-3 In stock: 229116 pcs RFQ		TLV809K33DBVT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 209205 pcs RFQ
	TLV809L30DBVT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.64V SOT23-3 In stock: 182640 pcs RFQ		TLV809K33DBZR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 140247 pcs RFQ
	TLV810MDBZR Manufacturers: N/A Description: IC VOLT SUPERVISR 4.38V SOT23-3 In stock: 396126 pcs RFQ		TLV809K33DBVR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 427288 pcs RFQ
	TLV809J25DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.25V SOT23-3 In stock: 127686 pcs RFQ		TLV809K33DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 113449 pcs RFQ
	TLV809L30DBZR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.64V SOT23-3 In stock: 374608 pcs RFQ		TLV810MDBZT Manufacturers: N/A Description: IC VOLT SUPERVISR 4.38V SOT23-3 In stock: 323163 pcs RFQ