

N/A



Image may be representation. See specifications for product details.

Part Number:	LM3705XBBP-232
Manufacturer/Brand:	N/A
Product description	IC MPU SUPERVISR 2.32V 9MICROSMD
Datasheets:	
RoHs Status	 Contains lead / RoHS non-compliant
Stock Condition	4286 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION









Specifications of LM3705XBBP-232

PART NUMBER	LM3705XBBP-232
MANUFACTURER	N/A
DESCRIPTION	IC MPU SUPERVISR 2.32V 9MICROSMD
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
QUANTITY AVAILABLE	4286 pcs
DATA SHEET	
VOLTAGE - THRESHOLD	2.32V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	9-μSMD (1.41x1.41)
SERIES	-
RESET TIMEOUT	20 ms Minimum
RESET	Active High
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	9-VFBGA
OUTPUT	Push-Pull, Totem Pole
OTHER NAMES	*LM3705XBBP-232 LM3705XBBP-232CT LM3705XBBP232
OPERATING TEMPERATURE	-40°C ~ 85°C (TJ)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	3 (168 Hours)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DETAILED DESCRIPTION	Supervisor Push-Pull, Totem Pole 1 Channel 9-μSMD (1.41x1.41)
BASE PART NUMBER	LM3705

Related Tags

LM3705XBBP-232	LM3705XBBP-232 Distributor	LM3705XBBP-232 Supplier
LM3705XBBP-232 Price	LM3705XBBP-232 Pictures	LM3705XBBP-232 Image
LM3705XBBP-232 PDF Datasheet	LM3705XBBP-232 Download Datasheet	LM3705XBBP-232 Datasheet
LM3705XBBP-232 Stock	Buy LM3705XBBP-232	Buy LM3705XBBP-232
LM3705XBBP-232	Supplier	Distributor

Related Products

 RFQ	LM3705XBMM-232/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 2.32V 10MSOP In stock: 3655 pcs	 RFQ	LM3704YCMXM-308/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 10MSOP In stock: 116218 pcs
 RFQ	LM3704YBMMX-360 Manufacturers: N/A Description: IC MPU SUPERVISOR 10MSOP In stock: 5895 pcs	 RFQ	LM3704YCMXM-308/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 3.08V 10MSOP In stock: 87995 pcs
 RFQ	LM3704YBMM-360/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 3.60V 10MSOP In stock: 5604 pcs	 RFQ	LM3704YCMXM-232 Manufacturers: N/A Description: IC MPU SUPERVISOR 10MSOP In stock: 6520 pcs
 RFQ	LM3705XCMM-308/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 3.08V 10MSOP In stock: 4180 pcs	 RFQ	LM3705XBMM-463/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 4.63V 10MSOP In stock: 6386 pcs
 RFQ	LM3705XBBP-463 Manufacturers: N/A Description: IC MPU SUPERVISR 4.63V 9MICROSMD In stock: 3615 pcs	 RFQ	LM3705XCBP-308 Manufacturers: N/A Description: IC MPU SUPERVISR 3.08V 9MICROSMD In stock: 5140 pcs
 RFQ	LM3705XDBP-232 Manufacturers: N/A Description: IC MPU SUPERVISR 2.32V 9MICROSMD In stock: 6176 pcs	 RFQ	LM3704YCMXM-232/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 2.32V 10MSOP In stock: 99624 pcs