

N/A



Image may be representation. See specifications for product details.

TLV809K33DBZT

Part Number:	TLV809K33DBZT
Manufacturer/Brand:	N/A
Product description	IC VOLT SUPERVISOR 2.93V SOT23-3
Datasheets:	
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	113449 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION






Specifications of TLV809K33DBZT

PART NUMBER	TLV809K33DBZT
MANUFACTURER	N/A
DESCRIPTION	IC VOLT SUPERVISOR 2.93V SOT23-3
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	113449 pcs
DATA SHEET	
VOLTAGE - THRESHOLD	2.93V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	SOT-23-3
SERIES	-
RESET TIMEOUT	120 ms Minimum
RESET	Active Low
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	TO-236-3, SC-59, SOT-23-3
OUTPUT	Push-Pull, Totem Pole
OTHER NAMES	296-28210-1
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Push-Pull, Totem Pole 1 Channel SOT-23-3
BASE PART NUMBER	TLV809K33

Related Tags

TLV809K33DBZT	TLV809K33DBZT Distributor	TLV809K33DBZT Supplier
TLV809K33DBZT Price	TLV809K33DBZT Pictures	TLV809K33DBZT Image
TLV809K33DBZT PDF Datasheet	TLV809K33DBZT Download Datasheet	TLV809K33DBZT Datasheet
TLV809K33DBZT Stock	Buy TLV809K33DBZT	Buy TLV809K33DBZT
TLV809K33DBZT	Supplier	Distributor

Related Products

	TLV809J25DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.25V SOT23-3 In stock: 127686 pcs RFQ		TLV809L30DBVR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.64V SOT23-3 In stock: 347716 pcs RFQ
	TLV809KEVM-019 Manufacturers: N/A Description: EVAL MODULE FOR TLV809K33 In stock: 4017 pcs RFQ		TLV810MDBZR Manufacturers: N/A Description: IC VOLT SUPERVISR 4.38V SOT23-3 In stock: 396126 pcs RFQ
	TLV809K33DBVR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 427288 pcs RFQ		TLV809L30DBVT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.64V SOT23-3 In stock: 182640 pcs RFQ
	TLV809K33DBZR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 140247 pcs RFQ		TLV809K33DBVT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 209205 pcs RFQ
	TLV809J25DBVT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.25V SOT23-3 In stock: 104662 pcs RFQ		TLV809L30DBZR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.64V SOT23-3 In stock: 374608 pcs RFQ
	TLV809J25DBZR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.25V SOT23-3 In stock: 404687 pcs RFQ		TLV809L30DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.64V SOT23-3 In stock: 229116 pcs RFQ