




ISL88002IH23Z-T7A

Part Number:	ISL88002IH23Z-T7A
Manufacturer/Brand:	Intersil
Product description	IC VOLT SUPERVISOR 2.32V SOT23-3
Datasheets:	 ISL88002IH23Z-T7A.pdf
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	86190 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of ISL88002IH23Z-T7A

PART NUMBER	ISL88002IH23Z-T7A
MANUFACTURER	Intersil
DESCRIPTION	IC VOLT SUPERVISOR 2.32V SOT23-3
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	86190 pcs
DATA SHEET	 ISL88002IH23Z-T7A.pdf
VOLTAGE - THRESHOLD	2.32V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	SOT-23-3
SERIES	-
RESET TIMEOUT	140 ms Minimum
RESET	Active Low
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	TO-236-3, SC-59, SOT-23-3
OUTPUT	Open Drain or Open Collector
OTHER NAMES	ISL88002IH23Z-T7A-ND ISL88002IH23Z-T7ATR ISL88002IH23ZT7A
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	3 (168 Hours)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Open Drain or Open Collector 1 Channel SOT-23-3
BASE PART NUMBER	ISL88002

Related Tags

Intersil ISL88002IH23Z-T7A	ISL88002IH23Z-T7A Distributor	ISL88002IH23Z-T7A Supplier
ISL88002IH23Z-T7A Price	ISL88002IH23Z-T7A Pictures	ISL88002IH23Z-T7A Image
ISL88002IH23Z-T7A PDF Datasheet	ISL88002IH23Z-T7A Download Datasheet	ISL88002IH23Z-T7A Datasheet
ISL88002IH23Z-T7A Stock	Buy ISL88002IH23Z-T7A	Buy Intersil ISL88002IH23Z-T7A
Intersil ISL88002IH23Z-T7A	Intersil Supplier	Intersil Distributor
Intersil ISL88002IH23Z-T7A		

Related Products

 ISL88002IH23Z-TK Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.32 SOT-23 In stock: 137752 pcs RFQ	 ISL88002IH23Z-T Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.32V SOT23-3 In stock: 69049 pcs RFQ
 ISL88002IH26Z-T Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.63V SOT23-3 In stock: 149717 pcs RFQ	 ISL88002IH22Z-T7A Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.19V SOT23-3 In stock: 71550 pcs RFQ
 ISL88002IH26Z-T7A Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.63V SOT23-3 In stock: 87211 pcs RFQ	 ISL88002IH17Z-T7A Manufacturers: Intersil Description: IC VOLT SUPERVISOR 1.67V SOT23-3 In stock: 52323 pcs RFQ
 ISL88002IH22Z-TK Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.19 SOT-23 In stock: 124899 pcs RFQ	 ISL88002IH29Z-T Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.92V SOT23-3 In stock: 122548 pcs RFQ
 ISL88002IH29Z-T7A Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.92V SOT23-3 In stock: 48477 pcs RFQ	 ISL88002IH26Z-TK Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.63 SOT-23 In stock: 67194 pcs RFQ
 ISL88002IH22Z-T Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.19V SOT23-3 In stock: 120279 pcs RFQ	 ISL88002IH17Z-TK Manufacturers: Intersil Description: IC VOLT SUPERVISOR 1.67V SOT23-3 In stock: 128981 pcs RFQ