

NXP Semiconductors / Freescale

MC100ES6111FA

Part Number:	MC100ES6111FA
Manufacturer/Brand:	NXP Semiconductors / Freescale
Product description	IC CLK BUFFER 2:10 2.7GHZ 32LQFP
Datasheets:	
RoHs Status	 Contains lead / RoHS non-compliant
Stock Condition	3514 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION





Specifications of MC100ES6111FA

PART NUMBER	MC100ES6111FA
MANUFACTURER	NXP Semiconductors / Freescale
DESCRIPTION	IC CLK BUFFER 2:10 2.7GHZ 32LQFP
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
QUANTITY AVAILABLE	3514 pcs
DATA SHEET	
VOLTAGE - SUPPLY	2.375 V ~ 3.465 V
TYPE	Fanout Buffer (Distribution), Multiplexer
SUPPLIER DEVICE PACKAGE	32-LQFP (9x9)
SERIES	100ES
RATIO - INPUT:OUTPUT	2:10
PACKAGING	Tray
PACKAGE / CASE	32-LQFP
OUTPUT	ECL, PECL
OPERATING TEMPERATURE	-40°C ~ 110°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
INPUT	ECL, HSTL, PECL
FREQUENCY - MAX	2.7GHz
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
DETAILED DESCRIPTION	Clock Fanout Buffer (Distribution), Multiplexer IC 2:10 2.7GHz 32-LQFP
BASE PART NUMBER	MC100ES6111

Related Tags

MC100ES6111FA	MC100ES6111FA Distributor	MC100ES6111FA Supplier
MC100ES6111FA Price	MC100ES6111FA Pictures	MC100ES6111FA Image
MC100ES6111FA PDF Datasheet	MC100ES6111FA Download Datasheet	MC100ES6111FA Datasheet
MC100ES6111FA Stock	Buy MC100ES6111FA	Buy MC100ES6111FA
MC100ES6111FA	Supplier	Distributor

Related Products

 MC100ES6111ACR2 Manufacturers: IDT (Integrated Device Technology) Description: IC CLK BUFFER 2:10 2.7GHZ 32TQFP In stock: 6096 pcs RFQ	 MC100ES6130EJR2 Manufacturers: IDT (Integrated Device Technology) Description: IC CLK BUFFER 2:4 2GHZ 16TSSOP In stock: 6029 pcs RFQ
 MC100ES60T23EF Manufacturers: IDT (Integrated Device Technology) Description: IC TRNSLTR UNIDIRECTIONAL 8SOIC In stock: 5454 pcs RFQ	 MC100ES6111AC Manufacturers: IDT (Integrated Device Technology) Description: IC CLK BUFFER 2:10 2.7GHZ 32TQFP In stock: 3433 pcs RFQ
 MC100ES6139DT Manufacturers: NXP Description: IC CLOCK GENERATION CHIP 20TSSOP In stock: 3635 pcs RFQ	 MC100ES6111FAR2 Manufacturers: NXP Description: IC CLK BUFFER 2:10 2.7GHZ 32LQFP In stock: 4547 pcs RFQ
 MC100ES6130DT Manufacturers: NXP Description: IC CLK BUFFER 2:4 2.5GHZ 16TSSOP In stock: 4022 pcs RFQ	 MC100ES6130EJ Manufacturers: IDT (Integrated Device Technology) Description: IC CLK BUFFER 2:4 2GHZ 16TSSOP In stock: 6444 pcs RFQ
 MC100ES60T23EFR2 Manufacturers: IDT (Integrated Device Technology) Description: IC TRNSLTR UNIDIRECTIONAL 8SOIC In stock: 2917 pcs RFQ	 MC100ES6111AC Manufacturers: NXP Description: IC CLK BUFFER 2:10 2.7GHZ 32LQFP In stock: 6198 pcs RFQ
 MC100ES60T22EJR2 Manufacturers: IDT (Integrated Device Technology) Description: IC TRNSLTR UNIDIRECTIONAL 8TSSOP In stock: 7054 pcs RFQ	 MC100ES6111FA Manufacturers: IDT (Integrated Device Technology) Description: IC CLK BUFFER 2:10 2.7GHZ 32TQFP In stock: 3130 pcs RFQ