



TDK Corporation



HHM1918A2

Part Number:	HHM1918A2
Manufacturer/Brand:	TDK Corporation
Product description	BALUN 2.3GHZ-2.7GHZ 50/100 0402
Datasheets:	 HHM1918A2.pdf
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	1190924 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION



Specifications of HHM1918A2

PART NUMBER	HHM1918A2
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 2.3GHZ-2.7GHZ 50/100 0402
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	1190924 pcs
DATA SHEET	 HHM1918A2.pdf
SERIES	HHM
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±15°
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	0402 (1005 Metric)
OTHER NAMES	445-175601-2
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	0.8dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 100 Ohm
FREQUENCY RANGE	2.3GHz ~ 2.7GHz
DETAILED DESCRIPTION	RF Balun 2.3GHz ~ 2.7GHz 50 / 100 Ohm 0402 (1005 Metric)

Related Tags

TDK Corporation HHM1918A2	HHM1918A2 Distributor	HHM1918A2 Supplier
HHM1918A2 Price	HHM1918A2 Pictures	HHM1918A2 Image
HHM1918A2 PDF Datasheet	HHM1918A2 Download Datasheet	HHM1918A2 Datasheet
HHM1918A2 Stock	Buy HHM1918A2	Buy TDK Corporation HHM1918A2
TDK Corporation HHM1918A2	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1918A2		

Related Products

 HHM1932A2 Manufacturers: TDK Corporation Description: BALUN 862MHZ-894MHZ 50/100 0402 In stock: 1054239 pcs RFQ	 HHM1904C1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/75 0402 In stock: 47142 pcs RFQ
 HHM1927A4 Manufacturers: TDK Corporation Description: BALUN 1.805-2.17GHZ 50/100 0402 In stock: 319228 pcs RFQ	 HHM1906A1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/75 0402 In stock: 3696 pcs RFQ
 HHM2202SA2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 1.71-1.79GHZ 0603 In stock: 4048 pcs RFQ	 HHM1917A5 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 In stock: 335006 pcs RFQ
 HHM1904A1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/75 0402 In stock: 58057 pcs RFQ	 HHM22106C1 Manufacturers: TDK Corporation Description: RF DIR CPLR 700MHZ-2.7GHZ 0603 In stock: 1052355 pcs RFQ
 HHM1907B1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/50 0402 In stock: 307944 pcs RFQ	 HHM1903A4 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0402 In stock: 314972 pcs RFQ
 HHM2204SA1 Manufacturers: TDK Corporation Description: RF DIR COUPLR 1.71-1.785GHZ 0603 In stock: 237035 pcs RFQ	 HHM1946A1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 0402 In stock: 62622 pcs RFQ