




ISL88708IB829Z-TK

Part Number:	ISL88708IB829Z-TK
Manufacturer/Brand:	Intersil
Product description	IC SUPERVISOR MPU 2.92V 8-SOIC
Datasheets:	 ISL88708IB829Z-TK.pdf
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	73137 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of ISL88708IB829Z-TK

PART NUMBER	ISL88708IB829Z-TK
MANUFACTURER	Intersil
DESCRIPTION	IC SUPERVISOR MPU 2.92V 8-SOIC
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	73137 pcs
DATA SHEET	 ISL88708IB829Z-TK.pdf
VOLTAGE - THRESHOLD	2.92V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	8-SOIC
SERIES	-
RESET TIMEOUT	140 ms Minimum
RESET	Active High/Active Low
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	8-SOIC (0.154", 3.90mm Width)
OUTPUT	Open Drain, Push-Pull
OTHER NAMES	ISL88708IB829Z-TKTR
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Open Drain, Push-Pull 1 Channel 8-SOIC
BASE PART NUMBER	ISL88708

Related Tags

Intersil ISL88708IB829Z-TK	ISL88708IB829Z-TK Distributor	ISL88708IB829Z-TK Supplier
ISL88708IB829Z-TK Price	ISL88708IB829Z-TK Pictures	ISL88708IB829Z-TK Image
ISL88708IB829Z-TK PDF Datasheet	ISL88708IB829Z-TK Download Datasheet	ISL88708IB829Z-TK Datasheet
ISL88708IB829Z-TK Stock	Buy ISL88708IB829Z-TK	Buy Intersil ISL88708IB829Z-TK
Intersil ISL88708IB829Z-TK	Intersil Supplier	Intersil Distributor
Intersil ISL88708IB829Z-TK		

Related Products

 ISL88708IB831Z Manufacturers: Intersil Description: IC SUPERVISOR 3.09V 8-SOIC In stock: 71063 pcs RFQ	 ISL88707IB846Z Manufacturers: Intersil Description: IC SUPERVISOR 4.64V 8-SOIC In stock: 60696 pcs RFQ
 ISL88708IB831Z-TK Manufacturers: Intersil Description: IC SUPERVISOR MPU 3.09V 8-SOIC In stock: 57444 pcs RFQ	 ISL88707IP846Z Manufacturers: Intersil Description: IC SUPERVISOR MPU 4.64V 8DIP In stock: 4236 pcs RFQ
 ISL88708IP829Z Manufacturers: Intersil Description: IC SUPERVISOR MPU 2.92V 8DIP In stock: 4827 pcs RFQ	 ISL88708IB844Z-TK Manufacturers: Intersil Description: IC SUPERVISOR MPU 4.38V 8-SOIC In stock: 70973 pcs RFQ
 ISL88707IB846Z-TK Manufacturers: Intersil Description: IC SUPERVISOR MPU 4.64V 8-SOIC In stock: 74343 pcs RFQ	 ISL88708IP826Z Manufacturers: Intersil Description: IC SUPERVISOR MPU 2.63V 8DIP In stock: 5918 pcs RFQ
 ISL88708IB826Z-TK Manufacturers: Intersil Description: IC SUPERVISOR MPU 2.63V 8-SOIC In stock: 64798 pcs RFQ	 ISL88708IB826Z Manufacturers: Intersil Description: IC SUPERVISOR 2.63V 8-SOIC In stock: 57350 pcs RFQ
 ISL88708IB829Z Manufacturers: Intersil Description: IC SUPERVISOR 2.92V 8-SOIC In stock: 60416 pcs RFQ	 ISL88708IB844Z Manufacturers: Intersil Description: IC SUPERVISOR 4.38V 8-SOIC In stock: 62985 pcs RFQ