



TDK Corporation



Image may be representation. See specifications for product details.

HHM1917A5

Part Number:	HHM1917A5
Manufacturer/Brand:	TDK Corporation
Product description	BALUN 2.4GHZ-2.5GHZ 50/50 0402
Datasheets:	 HHM1917A5.pdf
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	335006 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION



Specifications of HHM1917A5

PART NUMBER	HHM1917A5
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 2.4GHZ-2.5GHZ 50/50 0402
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	335006 pcs
DATA SHEET	 HHM1917A5.pdf
SERIES	*
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	0402 (1005 Metric), 4 PC Pad
OTHER NAMES	445-175600-1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	RF Balun 0402 (1005 Metric), 4 PC Pad

Related Tags

TDK Corporation HHM1917A5	HHM1917A5 Distributor	HHM1917A5 Supplier
HHM1917A5 Price	HHM1917A5 Pictures	HHM1917A5 Image
HHM1917A5 PDF Datasheet	HHM1917A5 Download Datasheet	HHM1917A5 Datasheet
HHM1917A5 Stock	Buy HHM1917A5	Buy TDK Corporation HHM1917A5
TDK Corporation HHM1917A5	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1917A5		

Related Products

 HHM1918A2 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 0402 In stock: 1190924 pcs RFQ	 HHM1903A4 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0402 In stock: 314972 pcs RFQ
 HHM2202SA2 Manufacturers: TDK Corporation Description: RF DIR COUPLR 1.71-1.79GHZ 0603 In stock: 4048 pcs RFQ	 HHM1907B1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/50 0402 In stock: 307944 pcs RFQ
 HHM2204SA1 Manufacturers: TDK Corporation Description: RF DIR COUPLR 1.71-1.785GHZ 0603 In stock: 237035 pcs RFQ	 HHM1927A4 Manufacturers: TDK Corporation Description: BALUN 1.805-2.17GHZ 50/100 0402 In stock: 319228 pcs RFQ
 HHM1906A1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/75 0402 In stock: 3696 pcs RFQ	 HHM1904A1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/75 0402 In stock: 58057 pcs RFQ
 HHM1946A1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 0402 In stock: 62622 pcs RFQ	 HHM1932A2 Manufacturers: TDK Corporation Description: BALUN 862MHZ-894MHZ 50/100 0402 In stock: 1054239 pcs RFQ
 HHM1904C1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/75 0402 In stock: 47142 pcs RFQ	 HHM1903A1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0402 In stock: 212246 pcs RFQ