




ICL3223EIV

Part Number:	ICL3223EIV
Manufacturer/Brand:	Intersil
Product description	IC TXRX 2/2 FULL RS232 20TSSOP
Datasheets:	 ICL3223EIV.pdf
RoHs Status	 Contains lead / RoHS non-compliant
Stock Condition	3450 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of ICL3223EIV

PART NUMBER	ICL3223EIV
MANUFACTURER	Intersil
DESCRIPTION	IC TXRX 2/2 FULL RS232 20TSSOP
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
QUANTITY AVAILABLE	3450 pcs
DATA SHEET	 ICL3223EIV.pdf
VOLTAGE - SUPPLY	3 V ~ 5.5 V
TYPE	Transceiver
SUPPLIER DEVICE PACKAGE	20-TSSOP
SERIES	-
RECEIVER HYSTERESIS	500mV
PROTOCOL	RS232
PACKAGING	Tube
PACKAGE / CASE	20-TSSOP (0.173", 4.40mm Width)
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF DRIVERS/RECEIVERS	2/2
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DUPLEX	Full
DETAILED DESCRIPTION	2/2 Transceiver Full RS232 20-TSSOP
DATA RATE	250kbps
BASE PART NUMBER	ICL3223E

Related Tags

Intersil ICL3223EIV	ICL3223EIV Distributor	ICL3223EIV Supplier
ICL3223EIV Price	ICL3223EIV Pictures	ICL3223EIV Image
ICL3223EIV PDF Datasheet	ICL3223EIV Download Datasheet	ICL3223EIV Datasheet
ICL3223EIV Stock	Buy ICL3223EIV	Buy Intersil ICL3223EIV
Intersil ICL3223EIV	Intersil Supplier	Intersil Distributor
Intersil ICL3223EIV		

Related Products

 Intersil A Renesas Company ICL3223EIAZ-T Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20SSOP In stock: 115275 pcs RFQ	 ICL3223EIVZ-T Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20TSSOP In stock: 90161 pcs RFQ
 Intersil A Renesas Company ICL3223IA Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20SSOP In stock: 4940 pcs RFQ	 ICL3223ECVZ Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20TSSOP In stock: 44473 pcs RFQ
 Intersil A Renesas Company ICL3223IA-T Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20SSOP In stock: 3247 pcs RFQ	 Intersil A Renesas Company ICL3223EIAZ Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20SSOP In stock: 53561 pcs RFQ
 ICL3223EIV-T Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20TSSOP In stock: 3381 pcs RFQ	 Intersil A Renesas Company ICL3223EIA Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20SSOP In stock: 7095 pcs RFQ
 ICL3223EIVZ-T7A Manufacturers: Intersil Description: IC TXRX RS232 DUAL ESD 20TSSOP In stock: 53060 pcs RFQ	 ICL3223EIVZ Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20TSSOP In stock: 46319 pcs RFQ
 Intersil A Renesas Company ICL3223EIA-T Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20SSOP In stock: 4293 pcs RFQ	 ICL3223ECVZ-T Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20TSSOP In stock: 98640 pcs RFQ