



A Renesas Company

Intersil



Image may be representation. See specifications for product details.

X5083P-2.7

Part Number:	X5083P-2.7
Manufacturer/Brand:	Intersil
Product description	IC SUPERVISOR CPU 8K EE 8-DIP
Datasheets:	 X5083P-2.7.pdf
RoHs Status	 Contains lead / RoHS non-compliant
Stock Condition	5007 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of X5083P-2.7

PART NUMBER	X5083P-2.7
MANUFACTURER	Intersil
DESCRIPTION	IC SUPERVISOR CPU 8K EE 8-DIP
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
QUANTITY AVAILABLE	5007 pcs
DATA SHEET	 X5083P-2.7.pdf
VOLTAGE - THRESHOLD	2.63V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	8-PDIP
SERIES	-
RESET TIMEOUT	100 ms Minimum
RESET	Active Low
PACKAGING	Tube
PACKAGE / CASE	8-DIP (0.300", 7.62mm)
OUTPUT	Open Drain or Open Collector
OPERATING TEMPERATURE	0°C ~ 70°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Through Hole
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DETAILED DESCRIPTION	Supervisor Open Drain or Open Collector 1 Channel 8-PDIP
BASE PART NUMBER	X5083

Related Tags

Intersil X5083P-2.7	X5083P-2.7 Distributor	X5083P-2.7 Supplier
X5083P-2.7 Price	X5083P-2.7 Pictures	X5083P-2.7 Image
X5083P-2.7 PDF Datasheet	X5083P-2.7 Download Datasheet	X5083P-2.7 Datasheet
X5083P-2.7 Stock	Buy X5083P-2.7	Buy Intersil X5083P-2.7
Intersil X5083P-2.7	Intersil Supplier	Intersil Distributor
Intersil X5083P-2.7		

Related Products

 X5083P-2.7A Manufacturers: Intersil Description: IC SUPERVISOR CPU 8K EE 8-DIP In stock: 7073 pcs RFQ	 X5045S8ZT1 Manufacturers: Intersil Description: IC SUPERVISOR CPU 4K EE 8-SOIC In stock: 36704 pcs RFQ
 X5083PI-4.5A Manufacturers: Intersil Description: IC SUPERVISOR CPU 8K EE 8-DIP In stock: 5557 pcs RFQ	 X5083PI-2.7A Manufacturers: Intersil Description: IC SUPERVISOR CPU 8K EE 8-DIP In stock: 3359 pcs RFQ
 X5083P Manufacturers: Intersil Description: IC CPU SUPRV 8K EE RST LO 8DIP In stock: 4504 pcs RFQ	 X5045V14I Manufacturers: Intersil Description: IC SUPERVISOR CPU 4K EE 14-TSSOP In stock: 4582 pcs RFQ
 X5045V14I-2.7A Manufacturers: Intersil Description: IC SUPERVISOR CPU 4K EE 14-TSSOP In stock: 6132 pcs RFQ	 X5083PI-2.7 Manufacturers: Intersil Description: IC SUPERVISOR CPU 8K EE 8-DIP In stock: 4581 pcs RFQ
 X5045V14I-4.5A Manufacturers: Intersil Description: IC SUPERVISOR CPU 4K EE 14-TSSOP In stock: 4205 pcs RFQ	 X5045V14I-2.7 Manufacturers: Intersil Description: IC SUPERVISOR CPU 4K EE 14-TSSOP In stock: 4757 pcs RFQ
 X5083PI Manufacturers: Intersil Description: IC SUPERVISOR CPU 8K EE 8-DIP In stock: 5508 pcs RFQ	 X5083P-4.5A Manufacturers: Intersil Description: IC SUPERVISOR CPU 8K EE 8-DIP In stock: 4273 pcs RFQ