

N/A



Image may be representation. See specifications for product details.

CDCLVP110VFG4

Part Number:	CDCLVP110VFG4
Manufacturer/Brand:	N/A
Product description	IC CLK BUFFER 2:10 3.5GHZ 32LQFP
Datasheets:	
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	11455 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION












Specifications of CDCLVP110VFG4

PART NUMBER	CDCLVP110VFG4
MANUFACTURER	N/A
DESCRIPTION	IC CLK BUFFER 2:10 3.5GHZ 32LQFP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	11455 pcs
DATA SHEET	
VOLTAGE - SUPPLY	2.375 V ~ 3.8 V
TYPE	Fanout Buffer (Distribution), Multiplexer
SUPPLIER DEVICE PACKAGE	32-LQFP (7x7)
SERIES	-
RATIO - INPUT:OUTPUT	2:10
PACKAGING	Tray
PACKAGE / CASE	32-LQFP
OUTPUT	LVPECL
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	HSTL, LVPECL
FREQUENCY - MAX	3.5GHz
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
DETAILED DESCRIPTION	Clock Fanout Buffer (Distribution), Multiplexer IC 2:10 3.5GHz 32-LQFP
BASE PART NUMBER	CDCLVP110

Related Tags

CDCLVP110VFG4	CDCLVP110VFG4 Distributor	CDCLVP110VFG4 Supplier
CDCLVP110VFG4 Price	CDCLVP110VFG4 Pictures	CDCLVP110VFG4 Image
CDCLVP110VFG4 PDF Datasheet	CDCLVP110VFG4 Download Datasheet	CDCLVP110VFG4 Datasheet
CDCLVP110VFG4 Stock	Buy CDCLVP110VFG4	Buy CDCLVP110VFG4
CDCLVP110VFG4	Supplier	Distributor

Related Products

	CDCLVP1102RGTT Manufacturers: N/A Description: IC CLK BUFFER 1:2 2GHZ 16QFN In stock: 24348 pcs RFQ		CDCLVP110MVFRG4 Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 11462 pcs RFQ
	CDCLVP110VF Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 7934 pcs RFQ		CDCLVP1102EVM Manufacturers: N/A Description: EVALUATION MODULE FOR CDCLVP1102 In stock: 635 pcs RFQ
	CDCLVP110VFRG4 Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 15445 pcs RFQ		CDCLVP111VF Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 9064 pcs RFQ
	CDCLVP110MVFR Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 14837 pcs RFQ		CDCLVP111MVFREP Manufacturers: N/A Description: IC CLOCK BUFFER MUX 2:10 32LQFP In stock: 4577 pcs RFQ
	CDCLVP111RHBT Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32QFN In stock: 12166 pcs RFQ		CDCLVP110VFR Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 14446 pcs RFQ
	CDCLVP111RHBR Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32QFN In stock: 7954 pcs RFQ		CDCLVP1102RGTR Manufacturers: N/A Description: IC CLK BUFFER 1:2 2GHZ 16QFN In stock: 31588 pcs RFQ